

United States Department of the Interior BUREAU OF INDIAN AFFAIRS

COLORADO RIVER AGENCY

Route 1, Box O.C. Parker, Arizona 85344

IN REPLY REFER TO:

Land Operation - Power (602) 669-6121/224

AUG 28 1989

May Name

Mr. Paul Zurakowski Radiation Specialist Nuclear Regulatory Commission 1450 Maria Lane, Suite 210 Walnut Creek, California 94596

Dear Mr. Zurakowski:

The following actions have been taken to remedy the violations stated on Document No. 030-17576:

- 1. Records for performance tests have been complied by the manufacturer and will be sent to the agency in September 1989. All records or tests will be handled this way in the future.
- 2. Warning labels have been ordered for the depth moisture probes and will be placed on the probes upon arrival.
- 3. Shipping paper are now being utilized for all transport of hazardous materials.
- 4. Enclosed for submittal is the signed Safety Inspection Report.

If you have any questions please contact Mr. Peter Overton, Supervisory Soil Conservationist, at the above number.

Sir orely,

Superintendent.