

50-269, 270, 281

NOV 1 1974

- J. P. O'Reilly, Director, RO:I
- N. C. Moseley, Director, RO:II
- J. G. Keppler, Director, RO:III
- E. M. Howard, Director, RO:IV
- R. H. Engelken, Director, RO:V

SECURITY INSPECTION OF OCONEE STATION

The attached memorandum contains provisions that the Directorate of Licensing considers the minimum requirement for acceptable inspection and search procedures. Their position was generated as a result of inadequate search procedures described in inspection report Nos. 50-269/74-6, 50-270/74-5, and 50-287/74-8 prepared for a licensed power reactor in Region II; OCONEE STATION.

The provisions of the DL interpretation are provided for information and guidance until the requirement that "Identification and search of all personnel shall be made..." becomes a regulation for all licensees. This statement appears in Part 73.55(c) (1) of a proposed amendment to 10 CFR 73 that is presently at the Commission level.

John G. Davis, Deputy Director
for Field Operations
Directorate of Regulatory Operations

Enclosure:
As Stated Above

- cc: D. F. Knuth
- C. W. Kuhlman
- J. G. Whiteaker
- R. W. Houston, L
- H. D. Thornburg

MEMO
4

OFFICE	RO:MPPB	RO:ESSE	RO:D/DEO		
SURNAME	JWhiteaker:j	HThornburg	JDavis		
DATE	10/ /74	10/3/74	10/ /74		

8001020 956 Q