



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION II - SUITE 818
230 PEACHTREE STREET, NORTHWEST
ATLANTA, GEORGIA 30303



December 5, 1969

J. P. O'Reilly, Chief, Reactor Inspection and Enforcement Branch
Division of Compliance, Headquarters

DUKE POWER COMPANY (OCONEE 1, 2 AND 3), LICENSE NOS. CPPR-33, 34 AND 35,
DOCKET NOS. 50-269, 270 AND 287

The attached report of an inspection of the subject facility by our
inspectors on November 3-5, 1969, is forwarded for information. There
were no items of nonconformance detected during the inspection.

A program has been developed by Bechtel for repairing the containment
building liner plate laminations reported in CO Report No. 50-269/69-8.
This problem is considered resolved.

Two nonconformance items, detected during the previous inspection, involving
welding procedure and welder qualification practices have been corrected.

With the arrival of the second Unit 1 steam generator scheduled for December
and the Unit 1 reactor vessel scheduled for January 1970, the construction
pace should pick up considerably within the next two or three months.

W. C. Seidle
Senior Reactor Inspector

CO:II:WCS

Enclosure:

CO Rpt. Nos. 50-269/69-9, 270/69-8
and 287/69-8 (Murphy)

cc: E. G. Case, DRS
R. S. Boyd, DRL (2)
S. Levine, DRL (6)
D. J. Skovholt, DRL (3)
L. Kornblith, Jr., CO
R. W. Kirkman, CO:I
B. H. Grier, CO:III
D. I. Walker, CO:IV
R. W. Smith, CO:V
REC Files

8001 030 987

④