

IE FILE COPY




November 8, 1977

L77-376

Docket No. 50-346
License No. NPF-3

File: RR 2 (NP-33-77-79)

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Dear Mr. Keppler:

Reportable Occurrence NP-33-77-79
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: October 11, 1977

Enclosed find three copies of Licensee Event Report NP-33-77-79 with a supplemental information sheet, which is being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/JRL/bjs

Enclosures

cc: [REDACTED]
Office of Inspection and Enforcement
Encl: 30 copies Licensee Event Report
30 copies Supplemental Information Sheet

Mr. William G. McDonald, Director
Office of Management
Information and Program Control
Encl: 3 copies Licensee Event Report
3 copies Supplemental Information Sheet

8001150110

8001150 709

S