1) Jankon

IE FILE COPY



November 2, 1977

L77-375

Docket No. 30-346 License No. NPF-3 FILE: RR.2 (NP-33-77-78)

Mr. James G. Keppler Regional Director, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence NP-33-77-78 Davis-Besse Nuclear Power Station Unit 1 Date of Occurrence: October 11, 1977

Enclosed find three copies of Licensee Event Report NP-33-77-78 with a supplemental information sheet, which is being submitted in accordance with Technical Specification 6.9 to provide 30 day writter notification of the subject occurrence.

Yours truly,

Tem Danum Terry D. Murray

Station Superintendent Davis-Besse Nuclear Station

TDM/JRL/ljk

Enclosures

cc: Dr. Ernst Volgenau, Director

Office of Inspection and Enforcement

Encl: 30 copies Licensee Event Report

30 copies Supplemental Information Sheet

Mr. William G. McDonald, Director

Office of Management

Information and Program Control

Encl: 3 copies Licensee Event Report

3 copies Supplemental Information Sheet