

Docket No.: 50-346

JUL 7 1975

DISTRIBUTION:
 NRC PDR
 L PDR
 Docket File
 LWR 2-3 Rdg
 VAMoore
 FSchroeder
 LWR TCs
 ELD
 IE (3)
 LEngle
 EGoulbourne
 TR BCs
 LWR BCs
 ACRS (14)
 JMazetis

Mr. Lowell E. Roe
 Vice President
 Facilities Development
 Toledo Edison Company
 Edison Plaza
 300 Madison Avenue
 Toledo, Ohio 43652

Dear Mr. Roe:

In our telephone conversation on June 25, 1975, I indicated to you that a discrepancy exists in cable qualification information as presented in Sections 3.0 and 7.0 of the FSAR for Davis-Besse, Unit 1. We request that you clarify this discrepancy and amend the FSAR by providing the additional information as requested below.

Sections 3.11.2.1.5 and 3.11.2.2.1 states that cable samples were air-oven aged at 121°C for 168 hours prior to testing the cable under LOCA condition. Since the LOCA conditions inside and outside the primary containment are different (as shown in Table 7-4), we will require that the design conditions for the cable tests be identified, and the test criteria (i.e., basis for passing or failing) be provided.

In addition, you are requested to provide a summary of the results for the cable qualification tests.

Please advise us within seven days after receipt of this letter of your schedule for providing the information requested.

Sincerely,

A. Schwencer, Chief
 Light Water Reactors Branch 2-3
 Division of Reactor Licensing

ccs: See next page

OFFICE →	x7886/LWR2-3	C-LWR2-3:RL			
SURNAME →	LEngle	ASchwencer			
DATE →	7/7/75	7/7/75			

8001150793

A

ccs: Donald H. Hauser, Esquire
The Cleveland Electric Illuminating Co.
P. O. Box 5000, Room 610
Cleveland, Ohio 44101

Gerald Charnoff, Esquire
Shaw, Pittman, Potts, Trowbridge
and Madden
910 - 17th Street, N. W.
Washington, D. C. 20006

Leslie Henry, Esquire
Fuller, Seney, Henry & Hodge
300 Madison Avenue
Toledo, Ohio 43604

bccs: J. R. Buchanan, ORNL
T. B. Abernathy, DTIE

OFFICE →						
SURNAME →						
DATE →						