MEMO ROUTE SLIP Form AEC-93 (Rev. May 14, 1947) Ama 0240		See me about this. Note and return.	For signature.	For action. For information.
H. D. Thomburg, RO:HQ	INITIALS	Attached is a copy of Toledo Edison's response to the RO: III Inspection of July 17-18, 1974, RO Inspection		
	DATE	Report No. 050-346/74-05 which identified ten (10) violations related to containment vessel painting.		
FO (Name and unit)	INITIALS	I do not consider this response to be adequate and it does not address the corrective action, adequate		
	DATE	measurements to assure that these viole ions do not occur again, etc.		
TO (Name and unity)	INITIALS	REMARKS		
	DATE	Dive o	discussed	this with
D. M. Hunnicutt	REMARKS	Doyle	& will &	licensel,
PHONE NO. DATE 10/7/74	,		Fel 8	es that

USE OTHER SIDE FOR ADDITIONAL REMARKS

GPO: 1971 O - 445-469