



UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TELEPHONE
(312) 856-2660

DEC 5 1974

Toledo Edison Company
ATTN: Mr. Lowell E. Roe
Vice President, Power
Edison Plaza
300 Madison Avenue
Toledo, Ohio 43652

Docket No. 50-346

Gentlemen:

This refers to the inspection conducted by Messrs. Greger and Jorgensen of this office on November 5 and 6, 1974, of activities at the Davis Besse Nuclear Power Station, Unit 1 authorized by AEC Construction Permit No. CPPR-80 and to the discussion held with Mr. Evans and other members of your staff at the conclusion of the inspection.

A copy of our report of this inspection is enclosed and identifies the areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, interviews with plant personnel, and observations by the inspectors.

No violations of AEC requirements were identified within the scope of this inspection.

In accordance with Section 2.790 of the AEC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the AEC's Public Document Room. If this report contains any information that you or your contractors believe to be proprietary, it is necessary that you make a written application to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. Any such application must include a full statement of the reasons for which it is claimed that the information is proprietary, and should be prepared so the proprietary information identified in the application is contained in a separate part of the document. Unless we receive an application to withhold information or are otherwise contacted within the specified time period, the written material identified in this paragraph will be placed in the Public Document Room.

COPY SENT TO:

PDR ✓
LPDR ✓
NSIC
TIC

50-346
112P

800120073C

Q

DEC. 5 1974

Toledo Edison Company

- 2 -

No reply to this letter is necessary; however, should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely yours,

D. M. Hunnicutt, Chief
Construction and Engineering
Support Branch

Enclosure:
RO Inspection Report
No. 050-346/74-08

bcc: RO Chief, FS&EB
RO:HQ (4)
RO Files
Licensing (4)
DR Central Files
PDR
Local PDR
NSIC
TIC