APR 2 2 1075

Docket No. 50-346

The Toledo Edison Company
ATTN: Mr. Lowell E. Roe
Vice President
Facilities Development
Edison Plaza
300 Madison Avenue
Toledo, Ohio 43652

REF: DISCONTINUITY INDICATIONS IN RCP PIPE TO PUMP FIELD WELDS - FINAL REPORT

Gentlemen:

Thank you for your letter dated April 7, 1975 which forwarded a report pursuant to 10 CFR 50.55(e) regarding the above referenced item. Your report will be reviewed and evaluated and, should we require additional information concerning this matter, we will contact you.

Please refer to Control No. HO 2000 in future correspondence in reference to this item.

Your cooperation is appreciated.

Sincerely, Original signed by & G. Davis

John G. Davis
Deputy Director for
Field Operations
Office of Inspection
and Enforcement

bcc: PDR
LPDR
NSIC
TIC
REGION III

-IE-Contral Files

OFFICE FSEB FSEB, C DDFO

SURMANE RFWarnick/11t HDT Cornburg JGDavis

CATE 4/2//75 4/2//75 4/2//75

Form AEC-318 (Rev. 9-53) AECM 0240

TU. S. GOVERNMENT PRINTING OFFICEI 1974-526-186