

MAY 4 1976

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Lowell E. Roe
Vice President
Facilities Development
300 Madison Avenue
Toledo, Ohio 43652

REF: APPARENT DEFICIENCY IN THE INSTRUCTION MANUALS FOR THE ANALOG
AMPLIFIERS IN THE SAFETY FEATURES ACTUATION SYSTEM

Gentlemen:

Thank you for your letter dated April 20, 1976 which forwarded a report pursuant to 10 CFR 50.55(e) regarding the above item. Your report will be reviewed and evaluated and, should we require additional information concerning this matter, we will contact you.

Please refer to Control No. HO 1265 F3 in future correspondence in reference to this item.

Your cooperation is appreciated.

Sincerely,

Original signed by
D. Thompson

Dudley Thompson
Acting Director
Division of Field Operations
Office of Inspection and
Enforcement

bcc: w/cpy ltr dtd 4/20/76
PDR
LPDR
NSIC

TIC
Region III
Central Files
IE Files

OFFICE →	FCEB <i>RW</i>	C. FCEB <i>GW</i>	AD, DFO			
SURNAME →	RFWarrick:mk	GW Roy	DThompson			
DATE →	5/ 4 176	5/ 4 176	5/ 4 176			

8001300 717 5