

L. Lankam

*NP-33
77-82*

IE FILE COPY



November 15, 1977

L77-382

Docket No. 50-346
License No. NPF-3

FILE: RR.2 (NP-33-77-82)

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence NP-33-77-82
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: October 19, 1977

Enclosed find three copies of Licensee Event Report NP-33-77-82 with a supplemental information sheet, which is being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry Murray / JES

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/JRL/ljk

Enclosures

cc: Dr. Ernst Volgenau, Director
Office of Inspection and Enforcement
Encl: 30 copies Licensee Event Report
30 copies Supplemental Information Sheet

Mr. William G. McDonald, Director
Office of Management
Information and Program Control
Encl: 3 copies Licensee Event Report
3 copies Supplemental Information Sheet

8002040690