



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
199 ROOSEVELT ROAD  
GLEN ELLEN, ILLINOIS 60137

IF FILE COPY

JUL 28 1977

Docket No. 50-346

Toledo Edison Company  
ATTN: Mr. Lowell E. Roe  
Vice President  
Facilities Development  
Edison Plaza  
300 Madison Avenue  
Toledo, OH 43652

Gentlemen:

This refers to the investigation conducted on May 24-27, 1977, at the Davis-Besse Nuclear Power Plant Unit 1 by Messrs. C. C. Williams, F. J. Jablonski and J. E. Kohler, of activities authorized by NRC License No. CPER-80 and the discussions held at the conclusion of the inspection by Mr. Williams with yourself and other members of your staff on May 27, 1977.

A copy of our report of this investigation is enclosed and identifies areas examined during this investigation. Within these areas, the investigation consisted of interviews with an alleged, plant construction and management personnel, observations, examination and evaluation of plant as-built conditions, and examination of records.

This investigation focused on the alleged nonconforming construction activities relative to the blackout and penetration sealing activities performed by your site contractor, Brand Industrial Services Company. Further, this investigation included the impact of these allegations on the forthcoming testing of the emergency ventilation system relative to the configuration of the "negative pressure boundary." Four of the allegations were substantiated and resulted in the issuance of an immediate action letter on May 31, 1977.

During this investigation, certain of your activities were demonstrated to be in noncompliance with NRC requirements, as described in the enclosed Appendix A.

8002050634

JUL 28 1977

The corrective action which was undertaken by Toledo Edison Company following the inspection, and which was reported in our immediate action letter dated June 14, 1977, regarding our concerns regarding the meters not listed in Appendix A, attached to the NRC inspections at the site, is as follows: ...

In accordance with Section 2.700 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed investigation report will be placed in the NRC's Public Document Room, except as follows. If this report contains information that you or your employees believe to be proprietary, you must apply in writing to this office, within thirty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and must be prepared so that proprietary information identified in the application is confined in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

E. P. Robinson, Chief  
Director General Inspection and  
Engineering Support Branch

Enclosures:

- 1. Appendix A, Meters  
of 6/14/77
- 2. Investigation Report  
No. 50-246/77-22

cc w/enclos:

- Central Files
- ✓ Reproduction Unit NRC 206
- PER
- Local PPDR
- NSIC
- TIC
- U. Young Park, Power  
Siting Commission

<p><i>Handwritten notes:</i> Held in office Conduct of ...</p>	<p>RIII Williams/jb 7/28/77</p>	<p>RIII Jablonski Kahler</p>	<p>RIII Hayes</p>	<p>RIII Little</p>	<p>RIII Danielson</p>	<p>RIII Boishman</p>
--	---	--------------------------------------	-----------------------	------------------------	---------------------------	--------------------------