

Appendix A

NOTICE OF VIOLATION

Toledo Edison Company

Docket No. 50-316

Based on the investigation conducted on May 24-27, 1977, it appears that certain of your activities were in noncompliance with NRC requirements, as outlined below. This item is an infraction.

Contrary to Criteria V, Appendix B, to 10 CFR 50, the Davis-Besse Nuclear Power Station Final Safety Analysis Report, paragraph 17.1.1.5, and the Toledo Edison Nuclear Quality Assurance Procedures QAP No. 2050 and No. 5020, safety related activities related to penetration sealing within the Emergency Ventilation System boundary were performed without approved procedures and without the required engineering and quality assurance reviews.

POOR  
ORIGINAL

8002050637