

POOR
ORIGINAL

FEB 10 1973

Toledo Edison Company
ATTN: G. J. Sampson
Vice President, Power
Edison Plaza
Toledo, Ohio 43652

Docket No. 50-346
Ref. CDR-52

Gentlemen:

Thank you for your report dated February 12, 1973, concerning welders not qualified in accordance with the applicable codes that made tack welds in Class 1 piping installed in your Davis-Besse facility. The nondestructive tests of the affected welds and records relating thereto, will be reviewed during our continuing inspection program. Should additional information be required relating to this problem, you will be contacted through our office in Glen Ellyn, Illinois.

Your cooperation concerning this matter is appreciated.

Yours truly,

Original signed by
F. E. Kruesi

F. E. Kruesi, Director of
Regulatory Operations

bcc: L. Rogers, ES
P. A. Morris, RO
H. D. Thornburg, RO
R. H. Engelken, RO
R. S. Boyd, L
R. C. DeYoung, L
F. Schroeder, L
J. G. Keppler, RO
G. W. Reinmsth, RO
A. Schwencer, L

B. H. Grier, RO:III
M. Steele, RO
L. Reeder, RO
← DR Central Files
DR Reading Files
PDR
Local PDR
NSIC
DTIE, OR

RO	RO	RO	RO
DEWhitwell:elm	JBHenderson	RHEngelken	REKruesi
X-7451			
3/14/73	3/ /73	3/ /73	3/ /73

8002060754

S