



UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TELEPHONE
(312) 858-2660

MAY 3 1 1974

Toledo Edison Company
ATTN: Mr. Lowell Roe
Vice President, Power
Edison Plaza
300 Madison Avenue
Toledo, Ohio 43652

Docket No. 50-346

Gentlemen:

The enclosed DRO Bulletin No. 74-6 "Defective Westinghouse Type W-2 Control Switch Component" is sent to provide you with information obtained during recent RO inspections. This information may have applicability at your facility. The action requested on your part is identified in the enclosed Bulletin.

If you have any questions on the contents of this Bulletin, please do not hesitate to contact us.

Sincerely,

James G. Keppler
Regional Director

Enclosure:
DRO Bulletin No. 74-6

DR Central Files
RO Files
PDR
Local PDR

POOR
ORIGINAL

8002060 772 misc

LB
Q