



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION II
230 PEACHTREE STREET, N. W. SUITE 818
ATLANTA, GEORGIA 30303

April 29, 1976

K. V. Seyfrit, Reactor Technical Assistant Branch, Office of Inspection
and Enforcement, Headquarters

nm THRU: Norman C. Moseley, Director, Office of Inspection and Enforcement,
Region II

FLORIDA POWER CORPORATION, CRYSTAL RIVER 3 (DN 50-302), CONTAINMENT DOME
SEPARATION - REQUEST FOR TRANSFER OF LEAD RESPONSIBILITY

FPC has discovered a separation of the concrete of the containment dome.
(Morning report April 19, 1976) The utility is currently investigating
the extent of damage and evaluating methods for repairing the structure.
Enclosed is a copy of the preliminary notification issued by Region II
on April 19, 1976, and the preliminary 50.55e report from FPC, dated
April 21, 1976.

It is requested that lead responsibility for review and acceptance of
the repair method be transferred to Licensing.

F. J. Long

F. J. Long, Chief
Reactor Operations and Nuclear
Support Branch

Enclosures:

1. Preliminary Notification
2. FPC letter to NRC dated
April 21, 1976

cc: F. Jape, IE:II
C. E. Murphy, IE:II
H. D. Thornburg, IE:HQ

8008160303 S