



UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TELEPHONE
(312) 858-2660

December 6, 1974

Consumers Power Company
ATTN: Mr. Stephen H. Howell
Vice President
1945 West Parnall Road
Jackson, Michigan 49201

Docket No. 50-329
Docket No. 50-330

Gentlemen:

The enclosed RO Bulletin requests action by you with regard to your power reactor facilities with operating license or construction permit.

Should you have questions regarding this Bulletin or actions requested of you, please contact this office.

Sincerely yours,

James G. Keppler
Regional Director

Enclosure:
RO Bulletin No. 74-15

"Approved by GAO, B-180225 (RO072), clearance expires 7-31-77. Approval was given under a blanket clearance specifically for identified generic problems."

bcc: DR Central Files
RO Files
PDR
Local PDR
OGC, Beth, P-506A
(GC) (2)
Ronald Callen
Dr. Wayne E. North
Myron M. Cherry

THIS DOCUMENT CONTAINS
POOR QUALITY PAGES

8006120 739

Ⓟ

CB

MISAPPLICATION OF CUTLER-HAMMER THREE POSITION MAINTAINED SWITCH MODEL NO. 10250T

An abnormal occurrence report submitted by the Wisconsin Public Service Corporation indicates a potential problem with Cutler-Hammer switches of Model No. 10250T which could effect the performance of control systems in which they are used.

Description of Circumstances:

The emergency diesel generators at Kewaunee Nuclear Power Plant received an automatic start signal. One of the diesels failed to start even though the local mode switch appeared to be in the "AUTO" position. Investigation by the licensee revealed a "dead" area between the "OFF" and "AUTO" positions of the Cutler-Hammer three position maintained switch, Model No. 10250T4023. It was determined that the switch could be positioned so that it appeared to be in "AUTO" but was actually in a position between "AUTO" and "OFF" such as to prevent either automatic starting of the diesel or actuation of the "NOT IN AUTO" annunciator. The same switch was installed on each of the two General Motors diesel generators supplied to the Kewaunee plant by the Western Engine Corporation.

Investigation by the AEC has revealed the use of Cutler-Hammer Model No. 10250T4023 switches in control panels for Fairbanks Morse diesel generators at one power reactor facility and in the emergency switching logic for the hydro emergency power source at another.

While this potential problem has been identified with the use of the Cutler-Hammer Model No. 10250T4023 switch, all switches of the basic Cutler-Hammer three position maintained Model No. 10250T are subject to potential malfunction similar to that described above.

Action Requested of Licensees:

Review the use, or planned use in the case of facilities under construction, of Cutler-Hammer three position maintained switches of basic Model No. 10250T in safety-related systems of your power reactor facilities, and:

1. If such switches are in use, or planned for use, in safety-related systems, notify this office in writing within 30 days of the extent of their use and what action you have taken or plan to take to prevent malfunction of the type described above. Your written notification should include the date(s) when your actions in response to this Bulletin were or will be completed.
2. If you find from your review that switches of the type described above are not in use, or planned for use, in safety-related systems of your power reactor facilities notify this office of this finding within 30 days.

*dupe of
800600546*