U.S. NUCLEAR REGULATORY COMMISSION

OFFICE OF INSPECTION AND ENFORCEMENT

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

Minnea Polis, Minnesota 55422 Glen Ellyn, IL 60137		
070-02902	SNM-1854	6/9/80
'ommission's rules and regulations and the c	ctivities conducted under your license as they relate onditions of your license. The inspection consisted of nd observations by the inspector. The findings as a res	selective examinations of procedures and repr
No items of noncompliance or un	nsafe conditions were found.	
The following items of noncompliance	related to records, signs, and labels were found	
A. Rooms or areas were not prop	erly posted to indicate the presence of a RADI	ATION AREA. 10 CFR 20.203(b) or 34.
B. Rooms or areas were not prop 10 CFR 20.203(c) (1) or 34.4	perly posted to indicate the presence of a HIGH 2	RADIATION AREA.
C. Rooms or areas were not prop 10 CFR 20.203(d)	perly posted to indicate the presence of an AIR	BORNE RADIOACTIVITY AREA.
D. Rooms or areas were not prop	perly posted to indicate the presence of RADIO	ACTIVE MATERIAL. 10 CFR 20.203(
E. Containers were not properly 10 CFR 20.203(f) (1) or (f) (2)	labeled to indicate the presence of RADIOACT 2)	TIVE MATERIAL.
F. A current copy of 10 CFR 20 made available. 10 CFR 20.20	, a copy of the license, or a copy of the operation (b)	ng procedures was not properly posted of
☐ G. Form NRC-3 was not properly	posted. 10 CFR 20.206(c)	
H. Records of the radiation expo	sure of individuals were not properly maintaine	ed. 10 CFR 20.401(a) or 34.33(b)
☐ I. Records of surveys or disposal	is were not properly maintained. 10 CFR 20.40	01(b) or 34.43(d)
J. Records of receipt, transfer, d 10 CFR 30.51, 40.61 or 70.51	isposal, export or inventory of licensed materia	al were not properly maintained.
K. Records of leak tests were not	maintained as prescribed in your license, or 10) CFR 34.25(c)
☐ L. Records of inventories were n	ot maintained. 10 CFR 34.26	
M. Utilization logs were not main	ntained. 10 CFR 34.27	
N. Records of radiation survey in	f radiation survey instrument calibration were not maintained. 10 CFR 34.24	
O. Records of teletherapy electric	al interlock tests were not maintained as prescribed in your license.	
P. Other	0,1	
	Robert E. Dung	in
The NRC Inspector has explained noncompliance will be corrected w	and I understand the items of noncompliant within the next 30 days.	pector) ce listed above. The items of

ORIGINAL TO LICENSEE