1750 Chestnut Street Towar II

FINARSHIE // LLEY ALM-CROTH

ひょうせい いううう じってい さいううち

July 21, 1980

Mr. James P. O'Reilly, Director J.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE REPORT SQR0-50-327/80101

The enclosed report provides details concerning the steam generator level indicator 1-LL-3-51 which was reading 10% higher than the other two redundant indicators. This report is submitted in accordance with Sequoyah unit 1 Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calicoun Director of Nuclear Power

Enclosure (3) cc (Enclosure): Director (3) Office of Management Information and Program Control U.S. Nuclear Regulatory Commission Washington, DC 20555

Director (40) Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555

Mr. Bill Lavallee Nuclear Safety Analysis Center Palo Alto, California 94303

Mr. W. T. Cottly, NRC Inspector, Sequoyah

THIS DOCUMENT CONTAINS POOR QUALITY PAGES

8007290 822