

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37404

400 Chestnut Street Tower II

TIC
50-259
260
296

JUL 31 AM 11:39

July 28, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

OFFICE OF INSPECTION AND ENFORCEMENT BULLETIN 80-16 - RII:JPO
50-259, -260, -296 - BROWNS FERRY NUCLEAR PLANT

In response to your June 27, 1980, letter which transmitted OIE Bulletin 80-16, we have completed our investigations for the Browns Ferry Nuclear Plant. Our investigations have revealed that none of the Rosemount Model 1151 or 1152 pressure transmitters with the output codes "A" or "D" are installed in any safety-related application. If you have any questions regarding this subject, please call Jim Domer at FTS 857-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager
Nuclear Regulation and Safety

cc: U.S. Nuclear Regulation and Safety
Office of Inspection and Enforcement
Division of Reactor Operations Inspection
Washington, DC 20555