

UNITED STATES

ATOMIC ENERGY COMMISSION DIRECTORATE OF REGULATORY OPERATIONS REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

TELEPHONE (312) 858-2660

September 26, 1972

J. B. Henderson, Chief, Reactor Construction Branch Directorate of Regulatory Operations, Headquarters

SUPPLEMENTAL REPORT OF INSPECTION (RO REPORT NO. 999-37/72-01)
VENDOR INSPECTION REPORT
HITACHI/BABCOCK HITACHI KK, KURE CITY, JAPAN
NEWBOLD ISLAND UNIT 1 REACTOR PRESSURE VESSEL
PUBLIC SERVICE ELECTRIC AND GAS COMPANY
DOCKET NO. 50-354

The attached supplement to the subject report is transmitted for information..

W. E. Vetter, Chief Reactor Construction Branch

Attachment: Supplemental Report No. 999-037/72-01

cc: R. B. Minogue, RS (3)

R. S. Boyd, L (2)

R. C. DeYoung, L (2)

D. J. Skovholt, L (3)

H. R. Denton, L (2)

R. H. Engelken, RO

H. D. Thornburg, RO

G. W. Reinmuth, RO

RO Files

DR Central Files