

Appendix A

NOTICE OF VIOLATION

Combustion Engineering, Inc.

Docket No. 70-36

Based on the inspection conducted on July 21-25, 1980, it appears that certain of your activities were in noncompliance with NRC requirements, as noted below. This item is a deficiency.

License Condition 2.1 of Amendment No. MPP-3 requires the licensee to follow the Fundamental Nuclear Material Control Plan as revised and amended in accordance with the provisions of 10 CFR 70.32(C).

Contrary to the above, and Section 7.2 of the Fundamental Nuclear Material Control Plan, four internal transfer forms did not bear the signatures of the individuals delegated to receive the material. The receiver's signatures were completely omitted from these four ICA to MBA transfers.