



CONNECTICUT YANKEE ATOMIC POWER COMPANY

HADDAM NECK PLANT

RR #1, BOX 127E, EAST HAMPTON, CONN. 06424

August 13, 1980

U. S. Nuclear Regulatory Commission
Region 1
Office of Inspection and Enforcement
631 Park Avenue
King of Prussia, Pennsylvania 19406

Attn: Mr. Boyce Grier,
Director

Reference: Facility Operating License No. DPR-61
Docket No. 50-213
Reportable Occurrence LER 80-11/3L

Dear Mr. Grier:

In accordance with the requirements of Connecticut Yankee Technical Specifications, Section 6.9.2.b.3, the attached Licensee Event Report concerning failure to perform required surveillance tests is hereby submitted.

The deficiencies were identified during a Quality Assurance audit.

An additional three (3) copies of the report are attached.

Very truly yours,

Richard H. Graves
Station Superintendent

RHG:RPT/jhb

Attachment: LER 80-11/31

cc: Dir., Office of Inspection and Enforcement, Washington, D. C. (30)
Dir., Office of Management Info. & Program Control, Wash., D.C. (3)
USNRC c/o Document Management Branch, Washington, D. C. (1)

8008190556

5