11.11	LICENSEE EVENT REPORT .
0	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8	N Y J A F 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 4 5 57 CAT 58 5
0 1 7 8	REPORT L 6 0 5 0 0 0 3 3 3 7 0 8 0 7 8 0 8 0 8 2 9 8 0 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 REPORT DATE 80
0 2	During normal shutdown, while conducting Surveillance Test F-ST-22A, the ADS timer
0 3	was found set at 112 seconds when TS Table 3.2-2 required a setpoint of 115 to 125
0 A	seconds. Operation of the timer 3 , 2 12 seconds early would not cause a significant
0 5	change in the operation of the system. The system was not required to be operable
0 6	with the reactor in the cold condition.
0 7	
012	
0 9	S F 11 E 12 E 13 I N S T R U 14 X 15 Z 16
	SEQUENTIAL REPORT NO. IER. RO EVENT YEAR REPORT NO. OCCURRENCE REPORT TYPE NO. O 6 9 0 3 L L 0 0 3 1 1 0 32
	ACTION FUTURE COMPONENT SUBMITTED FORM SUB. PRIME COMP. SUPPLIER S
10	The improper set point is attributed to drift. The timer was adjusted and made
1 1	fully operable on the following day. No additional action is required.
1 2	
1 3	
7 8	
1 5	FACILITY STATUS
1 6	ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA LOCATION OF RELEASE 36
7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 O O O O 37 Z 38 NA 9 11 12 13
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA 9 11 12 80
1 9	LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA NA NA
2 0	PUBLICITY ISSUED DESCRIPTION 45 NA NA NA NA NA NA NA NA
8000	020422 W. Verne Childs PHONE: 315-342-3840