



ARKANSAS POWER & LIGHT COMPANY
 POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000
 August 27, 1980

2-080-15

Mr. K. V. Seyfrit, Director
 Office of Inspection & Enforcement
 U. S. Nuclear Regulatory Commission
 Region IV
 611 Ryan Plaza Drive, Suite 1000
 Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2
 Docket No. 80-368
 License No. NPF-6
 Licensee Event Report No.
 80-037-01X-1
 (File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.8.b, attached is the subject report concerning "C" and "D" Safety Injection Tank (SIT's), which were found to have less than the specified amount of boron concentration (1731 PPM) during Mode 1 operation. This is a revision of a previous report submitted June 17, 1980.

Very truly yours,

David C. Trimble

David C. Trimble
 Manager, Licensing

DCT:GAC:ms
 Attachment

cc: Mr. Victor Stello, Jr., Director
 Office of Inspection and
 Enforcement
 U. S. Nuclear Regulatory Comm.
 Washington, D. C. 20555

Mr. Norman M. Haller, Director
 Office of Management and
 Program Analysis
 U. S. Nuclear Regulatory Comm.
 Washington, D. C. 20555

S