



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76012

bcc to DAC:ADM:
CENTRAL FILES
PDR:HQ
LPDR
~~TIC~~
NSIC

August 12, 1980


In Reply Refer To:
50-313/80-05
50-368/80-05

Arkansas Power and Light Company
ATTN: Mr. William Cavanaugh III
Vice President of Generation
and Construction
P. O. Box 551
Little Rock, Arkansas 72203

Gentlemen:

Thank you for your letters of July 8 and July 11, 1980, in response to our letter and Notice of Violation dated April 16, 1980. We have no further questions at this time and will review your corrective action during a future inspection.

Sincerely,


G. L. Madsen, Chief,
Reactor Operations and
Nuclear Support Branch

cc:
Arkansas Nuclear One
ATTN: J. P. O'Hanlon, General Manager
P. O. Box 608
Russellville, Arkansas 72801

8009040039*

Q



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

July 11, 1980

1-070-20

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Subject: Arkansas Nuclear One-Unit 1
Docket No. 50-313
License No. DPR-51
Inspection Report 313/80-05
(File: 0232)

Gentlemen:

Our letter of May 9, 1980 stated, in response to deficiency 313/80-05-02, that Generation and Construction Department procedures would be changed to provide for an adequate review of all Design Change Packages (DCP) per 10CFR50.59. Our review of the procedures, however, has shown that the current procedures are adequate to insure a proper review of DCP's in accordance with 10CFR50.59.

The deficiency does, however, indicate a need to inform those who do the review of the requirements for retention and performance of a written safety evaluation. To accomplish this, a memo has been sent from the Manager, Licensing to those Licensing Section personnel responsible for performing DCP reviews. This memo stated the requirements of 10CFR50.59 for the retention and performance of written safety evaluation, along with the Notice of Violation for deficiency 313/80-05-02. This should prevent further noncompliance.

Very truly yours,

David C. Trimble

David C. Trimble
Manager, Licensing

DCT:MAS:nak

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dupe of

8007220495