Forelli

## UNION ELECTRIC COMPANY 1901 GRATIOT STREET ST. LOUIS MISSOURI July 31, 1980

JOHN K. BRYAN

MAILING ADDRESS: P. O. BOX 140 ST. LOUIS, MISSOURI ESISS

Mr. James G. Keppler
Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

ULNRC-370

Dear Mr. Keppler:

## FINAL REPORT NSSS LATERAL SUPPORT ANCHOR BOLT NUTS CALLAWAY PLANT UNIT 1

On Friday, November 30, 1979, we provided Mr. W. A. Hansen verbal notification of a potential 50.55(e) report regarding out-of tolerance threads within NSSS lateral support anchor bolt nuts.

In our letter ULNRC-331, dated December 27, 1979, we requested that the submittal date of our final report on this matter be extended to March 1, 1980.

In our letter ULNRC-339, dated February 29, 1980 we requested that the submittal date of our final report on this matter be extended to August 1, 1980, due to the requirements for a physical test program.

We have concluded our reinspection and test program and have determined that had the nonconformance gone undetected there would have been no impact to the health and safety of the public and we are withdrawing this item as a significant deficiency.

This letter serves as our final report on this subject.

Very truly yours,

11/10

John K. Bryan (

WHZ/sla

cc: H. M. Wescott, Region III

B. H. Grier, Region I

Victor Stello, Jr., Director Office I&E

K. V. Seyfrit, Region IV

W. A. Hansen, NRC Resident Inspector, Callaway Plant

Missouri Public Service Commission

AUG 4 1980