

APPENDIX A

NOTICE OF VIOLATION

Teledyne Isotopes, Inc.
Westwood, New Jersey 07675
License Nos. 29-00055-06
29-00055-15

Docket Nos. 30-05219
30-14482

Based on the results of an NRC inspection conducted on June 13, 1980, it appears that certain of your activities were not conducted in full compliance with NRC regulations and the conditions of your license as indicated below:

- A. 10 CFR 20.201(b) requires you to make such surveys (evaluations) as may be necessary for you to comply with all sections of Part 20.

Contrary to this requirement, as of June 13, 1980, you failed to make such evaluations as were necessary to assure compliance with 10 CFR 20.303, a regulation that limits the disposal of licensed material by release to a sanitary sewerage system. Specifically, as of June 13, 1980, you failed to adequately evaluate the March 28, 1980 release to the sewerage system from the holdup tank of your precious metal decontamination facility. (License No. 29-00055-15)

This is an infraction.

- B. Condition 13 of License No. 29-00055-06 requires that you test your sealed sources containing byproduct material for leakage and/or contamination at intervals not to exceed six months.

Contrary to this requirement, as of the date of the inspection, June 13, 1980, you had not tested any of your sealed sources for contamination or leakage since August 20, 1979, an interval of more than six months.

This is an infraction.

8009150 387