	INSPE	CTION FINDINGS AND L	LICENSEE ACKNOWLS	EDGMENT
1. LICENSEE Berrien General Hospital 1250 Deans Hill Boad Berrien Center, HI 49102 3. DOCKET NUMBER(S) 070-02599 4. LICENSE NUMBER SNM-1736			2. REGIONAL OFFICE U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region III 499 Roosevelt Road Glen Ellyn, IL 60137	
				August 8, 1980
The in Comm entat	ission's rules and regulations and th we records, interviews with personne	e conditions of your license. T I, and observations by the inspi	he inspection consisted of ector. The findings as a rest	to radiation safety and to compliance with th selective examinations of procedures and repre ult of this inspection are as follows:
	No items of noncompliance or	unsafe conditions were for	und.	
The	following items of noncomplian	ce related to records, signs,	and labels were found:	
	A. Rooms or areas were not pr	operly posted to indicate t	he presence of a RADI/	ATION AREA. 10 CFR 20 1.03(b) or 34.4
	B. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42			
	C. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)			
	D. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e			
	E. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)			
	F. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted of made available. 10 CFR 20.206(b)			
	G. Form NRC-3 was not prope	rly posted. 10 CFR 20.206	(c)	
	H. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)			
	I. Records of surveys or dispo	sals were not properly main	ntained. 10 CFR 20.40	1(b) or 34.43(d)
	J. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51			
	K. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)			
	L. Records of inventories were not maintained. 10 CFR 34.26			
	M. Utilization logs were not maintained. 10 CFR 34.27			
	N. Records of radiation survey instrument calibration were not maintained. 10 CFR 34.24			
	O. Pecords of teletherapy electrical interlock tests were not inaintained as prescribed in your license.			
-	P. Other	and interioek tests were in	or manitanica as preser	lova ni your neense.
Long J	• Other		and the second second	
		and the second	at The Key	- Julian -
	e NRC Inspector has explaine ncompliance will be corrected			and an an an and the second
	(Date)		(Licensee Renresen	tative – Title or Position)