



Commonwealth Edison
Zion Generating Station
Shiloh Blvd. & Lake Michigan
Zion, Illinois 60099
Telephone 312/746-2084

DSB

September 9, 1980

Mr. James G. Keppler
Regional Director
Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
Glen Ellyn, Illinois 60137

Reference: Zion Generating Station
Docket No. 50-295/DPR-39
Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-295/80-07 for Zion Generating Station. This occurrence was reported to Region III, Directorate of Regulatory Operations by telephone on 8/27/80 and by telegram/mailgram on 8/27/80.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.a.2 which states that operation of the unit or affected systems when any parameter or operation subject to a limiting condition is less conservative than the least conservative aspect of the limiting condition for operation established in the Technical Specifications.

Very truly yours,

K. L. Graesser
Superintendent
Zion Station

Enclosure: Reportable Occurrence Report No. 50-295/80-07

Acc 2
S, 1/1

SEP 10 1980

8009160408

S