



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
511 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76012

28 AUG 1980

PDR-HQS

Docket No. 99900259/80-01

Combustion Engineering, Inc.
C-E Avery Division
Attn: Mr. P. F. Avery, Jr.
General Manager
Old Dover Road, P. O. Box 630
Newington, NH 03801

Gentlemen:

Thank you for your letters of July 3, 1980, and August 4, 1980 in response to our letters of June 6, 1980 and July 16, 1980 and discussion with your Ms. D. C. Almeda during a telephone call on July 15, 1980. We understand the Manufacturing Manager and Authorized Nuclear Inspector verified the Temper Bead Technique used during base metal repairs, and the master copy of D. W. P. WMC-10-11 has been corrected to reflect the actual weld repair sequence.

We have no further questions at this time and will review your corrective action during a future inspection.

Sincerely,

C. J. Hale

Uldis Potapovs, Chief
Vendor Inspection Branch

8009190 014