



Docket No. 50-344

UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

SEP 10 1980

TEEA

Mr. Charles Goodwin, Jr.
Assistant Vice President
Portland General Electric Company
121 S. W. Salmon Street
Portland, Oregon 97204

Dear Mr. Goodwin:

We have reviewed your response to our November 9, 1979 letter concerning those portions of your ECCS evaluation models, dealing with fuel cladding swelling and incidence of rupture.

We find that you have adequately confirmed the representations made in your behalf by your fuel supplier. We, therefore, conclude that your response is acceptable and that no further action is necessary at this time.

Sincerely,

A handwritten signature in cursive script, appearing to read "Robert A. Clark".

Robert A. Clark, Chief
Operating Reactors Branch #3
Division of Licensing

cc: See next page

8009260032

P

Mr. Charles Goodwin, Jr.
Portland General Electric Company

cc: Mr. J. W. Durham, Esquire
Vice President and Corporate Counsel
Portland General Electric Company
121 S.W. Salmon Street
Portland, Oregon 97204

Donald W. Godard, Supervisor
Siting and Regulation
Oregon Department of Energy
Labor and Industries Building
Room 111
Salem, Oregon 97310

Columbia County Courthouse
Law Library, Circuit Court Room
St. Helens, Oregon 97501

Michael Malmros, Resident Inspector
U. S. Nuclear Regulatory Commission
Trojan Nuclear Plant
P. O. Box 0
Rainier, Oregon 97043

Robert M. Hunt, Chairman
Board of County Commissioners
Columbia County
St. Helens, Oregon 97051

Director, Technical Assessment Division
Office of Radiation Programs (AW-459)
U. S. Environmental Protection Agency
Crystal Mall #2
Arlington, Virginia 20460

U. S. Environmental Protection Agency
Region X Office
ATTN: EIS COORDINATOR
1200 6th Avenue
Seattle, Washington 98101