

October 31, 1989

Mr. A. Bert Davis
Regional Administrator
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Byron Station Units 1 and 2
Additional Information for
Response to Inspection Report
50-454/89016 and 50-455/89018
NRC Docket Nos. 50-454 and 50-455

References: (a) August 29, 1989, letter from W. D. Shafer to Cordell Reed

(b) September 28, 1989, letter from R. A. Chrzanowski to A. B. Davis

Dear Mr. Davis:

In response to the Byron Inspection Report contained in reference (a), reference (b) was submitted. In that submittal, supplemental information regarding the Commonwealth Edison corporate review of the generic applicability of 10 CFR 50.59 safety evaluations was to be provided by November 1, 1989. This letter provides that information.

Commonwealth Edison has decided that if the following conditions exists;

- equipment is taken out-of-service or,
- there is degraded equipment or,

an abnormal line-up exists

then the plant condition will be further evaluated utilizing a screening process to determine if a 50.59 evaluation is required.

The specific screening criteria and the process itself is in under development. Further information describing the screening process will be forthcoming by December 15, 1989.

Please direct any questions regarding this matter to this office.

8911210090 891031 PDR ADOCK 05000454 Q PDC

ACO DURING

Nuclear Licensing Administrator

Very truly yours,

TE OI

/sc1:0339T:27

cc: Byron Resident Inspector
NRC Document Control Desk