



UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGION IV

URANIUM RECOVERY FIELD OFFICE
BOX 25325
DENVER, COLORADO 80225

NOV 21 1989

URFO:GR/A
Docket No. 40-8926
SUA-1492

State of Wyoming
Department of Environmental Quality
Herschler Building
122 West 25th Street
Cheyenne, Wyoming 82002

Gentlemen:

This refers to the announced radiation safety inspection conducted by Mr. G. R. Konwinski of this office on November 16, 1989, of the activities authorized by NRC Source Material License SUA-1492 and to the discussion of the findings held by the inspector with members of your staff at the conclusion of the inspection. The enclosed NRC Inspection Report 40-8926/89-01 documents this inspection.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, and observations by the inspector as they relate to tailings relocation and reclamation.

Within the scope of this inspection, no violations or deviations were identified.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in NRC's Public Document Room.


8911290009 891121
PDR ADOCK 04008926
C PLIC

JE07
1/1

NOV 21 1989

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,



Ramon E. Hall
Director

Enclosure:

Appendix A - NRC Inspection Report No. 40-8926/89-01

cc: Mark Moxley, Senior Environmental Specialist
210 Lincoln Street
Lander, Wyoming 82520