

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

Report Nos. 50-295/89032(DRSS); 50-304/89028(DRSS)

Dockets No. 50-295; 50-304

Licenses No. DPR-39; DPR-48

Licensee: Commonwealth Edison Company
Post Office Box 767
Chicago, IL 60690

Facility Name: Zion Nuclear Station, Units 1 and 2

Inspection At: Zion Station

Inspection Conducted: September 25-29, 1989

Type of Inspection: Routine, Unannounced Security

Inspectors:

G. M. Christoffer
G. M. Christoffer
Physical Security Inspector

11/20/89
Date

T. J. Madeda
T. J. Madeda
Physical Security Inspector

11/20/89
Date

Approved By:

J.R. Creed
J.R. Creed, Chief
Safeguards Section

11/21/89
Date

Inspection Summary

Inspection on September 25-29, 1989 (Report Nos. 50-295/89032(DRSS);
No. 50-304/89028(DRSS))

Areas Inspected: Training and Qualification; Management Effectiveness;
Security Organization; Records and Reports; Physical Barriers - Vital Areas;
Compensatory Measures; Access Control - Personnel.

Results: The licensee was in compliance with NRC requirements in the areas
inspected, except as noted below:

Access Control - Personnel: Contractor background screening program in one
case was not adequately implemented. (See Section 6 of Report Details.)

Physical Barriers - Vital Areas: The licensee failed to adequately maintain
a vital area barrier. (See Section 5 of Report Details.)

Inspection activities showed a decline in management effectiveness as
it relates to overall security program implementation.

(DETAILS - UNCLASSIFIED SAFEGUARDS INFORMATION)

8911290128 891121
PDR ADOCK 05000295
Q PDC

Enclosure Contains
SAFEGUARDS INFORMATION!
Upon Separation This
Page is Decontrolled