QUIVIRA MINING COMPANY

Octuber 6, 1989

RETURN ORIGINAL TO PDR. HQ.

Certified Mail Return Receipt Requested

Mr. Edward F. Hawkins, Chief Licensing Branch 1 Uranium Recovery Field Office U.S. Nuclear Regulatory Commission Box 25325 Denver, Colorado 80225

Re: License SUA-1473

Docket No. 40-8905

Request For An Amendment To License Condition 30

Crushed Drum Burial

Dear Mr. Hawkins:

Quivira Mining Company requests that license condition 30 for the above referenced source material license be amended. amendment is necessary as the current license condition allows burial of only plywood crates containing damaged drums. Quivira wishes to bury damaged yellowcake the for yellowcake drums. drums crates packaged in galvanized sheet metal or other suitable material as well. As such, Quivira submits a revised Standard Operating Procedure used in the Handling of Damaged Drums to reflect the necessary changes to bury galvanized sheet metal or other suitable material. These changes reflect the discussions via telephone conversations between Mr. Pete Garcia of your staff and myself.

The change from plywood packaging to other materials will not change any information previously submitted to your office on January 2, 1987 and March 5, 1987.

However, Quivira requests that the approved burial area for the crates be expanded to cover all of Pond 2 tailings area. Pond 2 has been previously approved by your office to receive material from decommissioning and stabilization process in license condition 32.

8911290134 891000 FDR ADOCK 04008905

DESIGNATED ORIGINAL

Certified By Enange. Hord

90-0030

Also attached is a check in the amount of \$150 to cover administration fees associated with the review of this submittal. If you have any questions please contact me at (505) 287-8851, extension 246.

Sincerely,

Quivira Mining Company

Bill Ferdinand

Bee Ludinand

Manager Radiation Safety and

Environmental Affairs

Attachments: (1) as stated

xc: M. Freeman

H. Whitacre

file