SAFETY INSPECTION

DCD /DCB

1. LICENSFE

Department of Nucleus Medicine
1700 OAK AM, Muskegon, MI 49442

SIGNATURE - LICENSEE

REGIONAL OFFICE

U.S. NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, IL 60137

3. DOCKET NUMBER(S)

5. DATE OF INSPECTION

630-13706

21-17971-11

	No Villa 16, 1989
icensee:	AND THE RESIDENCE OF THE PARTY
Regulatory Commission's (NRC) rules and regulation	nducted under your license as they relate to radiation safety and to compliance with the Nuclear and the conditions of your license. The inspection consisted of selective examinations of procedures and observations by the inspector. The findings as a result of this inspection are as follows:
1. Within the scope of this inspection, no violeti	were observed.
The inspector also verified the steps you have those actions at this time.	ken to correct the violations identified during the last inspection. We have no further questions on
	es checked below, were in violation of NRC requirements. equired to be posted in accordance with 10 CFR 19.11.
□ A	was not properly posted to indicate the presence
of a	was not properly posted to indicate the presence . 10 CFR 20.203(b), (c), (d), (e) or 34.42
Constitution toward to	
B. Containers located in	e material. 10 CFR 20.203(f)(1), or (f)(2).
frequencies, 10 CFR	of sealed sources were not performed at the proper License Condition Number
D. Records of	
10 CFR	or License Condition Number
E. Documents were not properly posted or o	rwise made available. 10 CFR 19.11.
F. Reports or notifications of	were not made in accordance
	or License Condition Number
Н	
[]·	
8911290162 8911	
REG3 LIC30	C