

NOV 24 1989

In Reply Refer To:  
License: 35-23461-01  
Docket: 30-22215/89-01

Eck View General Hospital  
ATTN: J. W. Finch, Administrator  
429 West Elm  
Hobart, Oklahoma 73651

Gentlemen:

This refers to the routine, unannounced radiation safety inspection conducted by Mr. Selvan Rajendran of this office on August 24 and 25, 1989, of the activities authorized by NRC Byproduct Material License 35-23461-01, and to the discussion of our findings held by the inspector with members of your staff at the conclusion of the inspection. The enclosed NRC Inspection Report 30-22215/89-01 documents this inspection.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observations by the inspector.

During the inspection, certain of your activities appeared to be in violation of NRC requirements. We are releasing this report at this time for your information. You are encouraged to review our findings and take corrective action as you believe appropriate. You will be notified by separate correspondence of our decision regarding enforcement action based on the findings of this inspection. No written response is required at this time; however, you may, if you wish, provide a response that describes any corrective actions taken.

This letter also confirms the telephone discussion between Mr. Charles L. Cain of my staff and Mr. J. W. Finch on November 22, 1989, concerning our request to conduct a telephonic management conference. The time and date agreed upon was 10 a.m., on November 29, 1989. This conference will address the findings of the NRC inspection referenced above and your response to these findings.

The inspection findings indicate a weakness in the management control of your radiation safety program such that if these or similar violations were to continue, a breakdown in licensed activities could occur. Please be prepared to discuss your corrective actions during the telephonic conference.

RIV:NMIS  
SRajendran:jc  
11/24/89

C:NMIS  
CLCain  
11/24/89

D:DRSS  
ABBeachey  
11/26/89

8912010229 891124  
REG4 LIC30  
35-23461-01 PNU

IE-07  
11

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

*Original Signed By:*

**A. B. BEACH**

A. Bill Beach, Director  
Division of Radiation Safety  
and Safeguards

Enclosures:

Appendix - NRC Inspection Report  
30-22215/89-01

cc w/encls:

Oklahoma Radiation Control Program Director

bcc:

DMB - Original (IE-07)

RDMartin

ABBeach

LAYandell

LShea, RM/ALF (AR-2015)

CLCain

RJEverett

SRajendran

NMIS

MIS System

RIV Files (2)

RSTS Operator

REHall, URFO