



November 22, 1989

Mr. A. Bill Beach, Director  
Division of Radiation Safety & Safeguards  
United States Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Dr., Suite 1000  
Arlington, TX 76011

RE: License: 35-1402-02  
Docket: 030-29055/89-01

Gentlemen:

In reply to your letter of October 13, 1989, regarding violations found at this facility, we respectfully submit the following:

1. The permanent radiation monitor installed in the teletherapy room was not checked daily with a dedicated check source for proper operation. This was immediately changed, and the monitor is now checked daily with a dedicated source with the proper documentation.
2. A. Due to an oversight, all records of full calibration measurements did not contain the model number and serial number of the instruments used to calibrate the teletherapy unit. This has been corrected by the radiation physicist, and will continue to be on all records of calibration.  
B. Due to oversight, all records of the periodic spot checks did not contain the model number and serial number of the instruments used to measure the output of the teletherapy unit. This also has been corrected by the radiation physicist, and will be included on all records of the periodic spot checks.

Very truly yours,

*James R. Powers*  
James R. Powers  
Senior Vice-President

8912050210 891122  
REG4 LIC30  
35-14042-02 FDC