NRC Form 581 (12-81) 10 CFA 2.201

SAFETY INSPECTION

MATHY CONSTRUCTION COMPANY P.O. BOX 189 915 COMMERCEAL COURT ON ALASKA, WI 54650			UUS. NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, IL 60137	
030-140	81	48-187		16 November 1989
egulatory Commissions (Ind representative records,	NRC) rules and regulation interviews, with personanthis inspection, no violet	ns and the conditions of y nel, and observations by the tions were observed.	your license. The inspense inspector. The finding	adiation safety and to compliance with the Nuclear ction consisted of selective examinations of procedures ngs as a result of this inspection are as follows: g'the last inspection. We have no further questions on
	on certain of your activit OF VIOLATION which	ties, as checked below, we is required to be posted	n accordance with 10 (
c	te the presence of radios	ctive material, 10 CFR 2	Licens	were not properly maintained
	cations of	otherwise made avaable.		were not made in accordanc
	8912070389 8 EG3 LIC30 88-18722-01	91116 — PDC		
is statement of corrective NRC.	O days the actions descree actions is made in acco	ibed by me to the inspect	or will be taken to corrents of 10 CFR 2.201.	ect the violations identified in the items checked above No further response will be submitted unless required b