

CONVERSATION RECORD

TIME 1:30 PM DATE 12/1/89

TYPE VISIT CONFERENCE TELEPHONE

INCOMING
 OUTGOING

ROUTING	
NAME/SYMBOL	INT
E P/ACK/TIME	
V T/ADPE/DATE (BUCKET)	

Location of Visit/Conference:

NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU
CHUCK MALODY

ORGANIZATION (Office, dept., etc.)
ADVANCED NUCLEAR FUELS CORP. (509) 375-8537

TELEPHONE NO.

SUBJECT
30-inch diameter cylinders manufactured by Columbiara Boiler Company

SUMMARY

On December 1, 1989, I informed ANF's Mr. Chuck Malody of the Model 30B UF₆ cylinders which failed recertification because of cylinder wall thinning. I also posed the following questions:

- 1) How many, if any, 30-inch diameter (30A and 30B) cylinders does Allied-Signal possess that were manufactured by Columbiara Boiler Company?
- 2) If Allied-Signal does possess any 30-inch diameter cylinders manufactured by this company, how many were manufactured in 1979?
- 3) In general, how many UF₆ cylinders have failed recertification because of wall thinning?

Later on the same day, Mr. Malody stated that ANF had never purchased cylinders fabricated from the subject company and that no cylinders had failed recertification because of wall thinning.

ACTION REQUIRED

N/A

8912110216 891201
PDR ADOCK 07001257
C PNU

NAME OF PERSON DOCUMENTING CONVERSATION
W. SCOTT KINGSTON

SIGNATURE
W. Scott Kingston

DATE
12/1/89

ACTION TAKEN

SIGNATURE

DOCKETED
USNRC
DEC 06 1989
NMSS
MAIL SECTION
DOCKET CLERK

TELE

DATE

DEC 06 1989
NMSS
MAIL SECTION
DOCKET CLERK

DATE
12/1/89

addit wj

DOCKET NO. 70-1257
CONTROL NO. 26142
DATE OF DOC. Dec. 1, 1989
DATE RCVD. Dec. 6, 1989
FCUF PDR
FCAF _____ LPDR _____
I & E REF.
SAFEGUARDS _____
OTHER _____
FCTC _____
DATE 12/6/89 INITIAL SAC

