

NOTICE OF VIOLATION

Akron Industrial Services, Inc.

License No. 34-24673-01

As a result of the inspection conducted on November 8, 1989, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, (1989) (Enforcement Policy) the following violations were identified:

- 1.0. 10 CFR 34.31 (c) requires each licensee to maintain for three years the records of training for each radiographer, including written tests.

Contrary to the above, the licensee failed to maintain a record of a written test completed on April 17, 1989 by a radiographer employed by the licensee.

This is a Severity Level V violation (Supplement VI).

- 2.0. License Condition No. 17 requires that licensed material be possessed and used in accordance with statements, representations and procedures contained in an application dated March 4, 1986. Section RS-GP-15 of the Radiation Safety Manual submitted with the application states in Paragraph 3.2 that a quarterly review shall be conducted on each radiographer and/or Radiographer's Assistant for compliance with company procedures and NRC Regulations.


Contrary to the above, the licensee failed to perform the required quarterly review during the period from May 1, 1989, to the day of the inspection, November 8, 1989.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) the corrective steps that have been taken and the results achieved; (2) the corrective steps that will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated

12/8/89


D. J. Srentawski, Chief
Nuclear Materials Safety
Section 1