

## UNITED STATES

## **NUCLEAR REGULATORY COMMISSION**

REGION !V

URANIUM RECOVERY FIELD OFFICE BOX 25325 DENVER, COLORADO 80225

NOV 21 1989

URFO:GRK Docket No. 40-8926 SUA-1492

State of Wyoming Department of Environmental Quality Herschler Building 122 West 25th Street Cheyenne, Wyoming 82002

Gentlemen:

This refers to the announced radiation safety inspection conducted by Mr. G. R. Konwinski of this office on November 16, 1989, of the activities authorized by NRC Source Material License SUA-1492 and to the discussion of the findings held by the inspector with members of your staff at the conclusion of the inspection. The enclosed NRC Inspection Report 40-8926/89-01 documents this inspection.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, and observations by the inspector as they relate to tailings relocation and reclamation.

Within the scope of this inspection, no violations or deviations were identified.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in NRC's Public Document Room.

8912140013 891121 PDR ADOCK 04008926 DE023

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Ramon E. Hall Director

Enclosure:

Appendix A - NRC Inspection Report No. 40-8926/89-01

cc: Mark Moxley, Senior Environmental Specialist

210 Lincoln Street Lander, Wyoming 82520