

DEC - 4 1989

In Reply Refer To:  
License: 42-01485-04  
Docket: 30-17243/89-02

Texas Nuclear Corporation  
ATTN: John Nelson, President  
P.O. Box 9267  
Austin, Texas 78766-9990

Gentlemen:

This refers to the routine, unannounced radiation safety inspection conducted by Mr. Selvan Rejendran of this office on September 12, 1989, of the activities authorized by NRC Byproduct Material License 42-01485-04, and to the discussion of our findings held by the inspector with members of your staff at the conclusion of the inspection. The enclosed NRC Inspection Report 30-17243/89-02 documents this inspection.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, and observations by the inspector.

No violations or deviations were identified.

The scope of this inspection was limited in that licensed operations were not reviewed at temporary job sites; however, a review of records and interviews of personnel revealed no apparent major problems.

No response to this letter is required. Should you have any questions concerning this letter or the enclosed report, we will be pleased to discuss them with you.

Sincerely,

*Original Signed By:*

CHARLES L. CAIN *for*

A. Bill Beach, Director  
Division of Radiation Safety and  
Safeguards

Enclosure:  
Appendix - NRC Inspection Report  
30-17243/89-02

cc:  
Texas Radiation Control Program Director

RIV: NMIS *AKC*  
SRajendran;lw  
12/1/89

C: NMIS *AKC*  
CLCain  
12/1/89

ID: DRSS *AKC*  
VABeach  
12/4/89

8912140376 891204  
REG4 LIC30  
42-01485-04 PNU

IE-07  
/

bcc:  
DMB - Original (IE-07)  
RDMartin  
ABBeach  
LAYandell  
LShea, RM/ALF (AR-2015)  
\*CLCain  
\*RJEverett  
\*Inspector  
\*NMIS  
\*MIS System  
\*RIV Files (2)  
\*RSTS Operator  
\*REHall, URFO  
  
\*W/766