RETURN ORIGINAL MARKET HO. PETROTOMICS COMPANY P.O. BOX 8509 SHIRLEY BASIN WY 82615 - TELE. MOV 1989

October 30, 1989

T121

Mr. Edward F. Hawkins U.S. Nuclear Regulatory Commission Uranium Recovery Field Office Region IV P.O. Box 25325 Denver, CO. 80225

Reference: License Condition 47 D - Source Materia SUA - 551

Dear Sir:

In accordance with the requirement of License Condition 47 D, we are submitting herewith a report on the results of the July 26, 1989, corrective action modifications. In addition, further modifications are proposed.

Five copies of the report are enclosed.

Attached is our check in the amount of \$150.00 for the application fee for this submittal as required by Paragraph 170.31 of Part 170. Please contact us if you have any questions.

Sincerely,

R.A./Juday

Supervisor

8912150079 891030 ADOCK 04006659

DESIGNATED ORIGINAL RAJ/mwb Certified By many C. Hook

90-0081