NRC Form 591	U.S. NUCLEAR REGULATORY COMMISSION		
(12:81) 10 CFR 2.201	SAFETY I	NSPECTION	
			DmB
1. LICENSEE		2. REGIONAL OFFIC	
Yanad Carl		U.S. Nuclear Regulatory Commission	
Nenell Corporation Po. Boy 669 Wynnewood, Oklahama 73098		RIV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011	
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)		5. DATE OF INSPECTION
30-12503/84-01	35-12622	-02E	11/27/85
Licensee		and the second s	
and representative records, interviews, with personn 1. Within the scope of this inspection, no violat	A and the conditions of you hel, and observations by the ions were observed. In taken to correct the violation ies, as checked below, were is required to be posted in a	in license. The inspection inspector. The findings ions identified during th in violation of NRC req accordance with 10 CFI	on consisted of selective examinations of procedures i as a result of this inspection are as follows: ne last inspection. We have no further questions on quirements.
Ctrequencies. 10 CFR		License (Condition Number
nequencies. To or n			
D Records of			were not properly maintained.
10 CFR		or License Condition N	umber ·
E. Documents were not properly posted or	otherwise made available 1	0 CFR 19.11.	
_			were not made in accordance
F. Reports or notifications of			the state of the second st
With to or H			
Пн			
L			
			and all a second se
	91127		
8912180027 8 REG4 LIC30 35-17622-02E	FDC		and the second
	P LIC.		
hereby state that within 30 days the actions descr	ibed by me to the inspector	will be taken to correct	the violations identified in the items checked above
This statement of corrective actions is made in acco the NRC.	ordance with the requiremen	a of 10 CFH 2.201. No	o further response will be submitted unless reduced of
		1. H.	TE-01
	1	1. Inthan	1 Janos -11/27/2
SIGNATURE - LICENSEE	DATE	SIGNATU	RE - NAC INSPECTOR DATE