Docket No. 50-213

Connecticut Yankee Atomic Power Company

ATTN: Mr. E. J. Mroczka

Senior Vice President - Nuclear

Engineering and Operations

P. O. Box 270

Hartford, Connecticut 06141

Gentlemen:

Subject: Inspection Report No. 50-213/89-22

A routine radiation safety inspection was conducted on November 13-17, 1989, at the Haddam Neck Station by Mr. T. Dragoun. Areas reviewed included training and qualification, auditing, internal exposure control and the new TLD dosimetry system.

During the course of this inspection one apparent violation of Technical Specification training requirements was identified as described in Appendix A. You are required to respond to this finding by following the instructions included in Appendix A. Your cooperation with us is appreciated.

Sincerely.

Original Signed By: Robert J. Bores

Ronald R. Bellamy, Chief Facilities Radiological Safety and Safeguards Branch Division of Radiation Safety and Safeguards

Enclosure: Inspection Report No. 50-213/89-22

cc w/encl:

W. D. Romberg, Vice Prosident, Nuclear Operations

D. B. Miller, Station Superintendent

D. O. Nordquist, Director of Quality Services

R. M. Kacich, Manager, Generation Facilities Licensing S. E. Scace, Station Superintendent, Millstone

Gerald Garfield, Esquire Public Document Room (PDR) Local Public Document Room (LPDR) Nuclear Safety Information Center (NSIC) NRC Resident Inspector State of Connecticut

IEO6

bcc w/encl: Region I Docket Room (with concurrences) Management Assistant, DRMA (w/o encl) DRP Section Chief A. Wang, LPM, NRR M. Conner, SALP Reports Only
J. Shedlosky, SRI, Haddam Neck
W. Raymond, SRI, Millstone 1&2
J. Dyer, EDO

RI: DRSS Dragoun/mk

12/7/89

12/12/89

for Bellamy

12/12/89 OFFICIAL RECORD COPY

IR HN 89-22 - 0002.0.0 12/07/89