

August 8, 1980

In reply, please
refer to LAC-7081

DOCKET NO. 50-409

Mr. James G. Keppler
Regional Director
U. S. Nuclear Regulatory Commission
Directorate of Regulatory Operations
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

SUBJECT: DAIRYLAND POWER COOPERATIVE
LA CROSSE BOILING WATER REACTOR (LACBWR)
PROVISIONAL OPERATING LICENSE NO. DPR-45
IE BULLETIN NO. 80-20 - FAILURES OF WESTINGHOUSE
TYPE W-2 SPRING RETURN TO NEUTRON CONTROL SWITCHES

Reference: (1) NRC Letter, Keppler to Linder,
dated July 31, 1980.

Dear Mr. Keppler:

Your letter (Reference 1) requested that we determine whether Westinghouse Type W-2 control switches with spring return to neutral position are used in safety-related applications at our facility.


We have determined that Westinghouse Type W-2 control switches with spring return to neutral position are not used in safety related applications at our facility.

Also, as requested in Reference 1, the estimated manpower expended in the conduct of the review and preparation of this report was 2.5 hours.

If there are any questions regarding this response, please contact us.

Very truly yours,

DAIRYLAND POWER COOPERATIVE



Frank Linder, General Manager

FL:WRN:af

cc: Director, Division of Reactor Operations Inspection
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8009090 006

AUG 21 1980