

72

POWER AUTHORITY OF THE STATE OF NEW YORK
JAMES A. FITZPATRICK NUCLEAR POWER PLANT



RAYMOND J. PASTERNAK
Resident Manager

P.O. BOX 41
Lycoming, New York 13093
315-342-3840

August 12, 1980
SERIAL: JAFP 80-643

50-333

Boyce H. Grier, Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406

SUBJECT: NRC I&E BULLETIN 80-19
FAILURES OF MERCURY-WETTED MATRIX RELAYS IN REACTOR PROTECTIVE
SYSTEMS OF OPERATING NUCLEAR POWER PLANTS DESIGNED BY
COMBUSTION ENGINEERING

Dear Mr. Grier:

The FitzPatrick Plant staff has completed a review of the subject Bulletin and determined that mercury-wetted relays are not used in the Reactor Protection System at the FitzPatrick Plant.

In view of this finding, no additional action is required.

Very truly yours,

Robert Baker for

RAYMOND J. PASTERNAK
RESIDENT MANAGER

RJP:VC:brp
Distribution:

Director, Division of Reactor
Operations Inspection
Washington, D.C. 20555

George T. Berry, PASNY, NYO
J. P. Bayne, PASNY, NYO
G. M. Wilverding, PASNY, NYO
H. N. Keith, PASNY, JAF
M. C. Cosgrove, PASNY, JAF
R. Baker, PASNY, JAF
Resident Inspector, JAF
Document Control Center

8009090 014