



UNITED STATES  
 NUCLEAR REGULATORY COMMISSION  
 REGION III  
 799 ROOSEVELT ROAD  
 GLEN ELLYN, ILLINOIS 60137

MAY 15 1980

State of Illinois  
 Department of Public Health  
 ATTN: Mr. Gary N. Wright, Chief  
 Division of Nuclear Safety  
 535 West Jefferson Street  
 Springfield, IL 62761

Gentlemen:

The enclosed IE Bulletin No. 80-07, Supplement No. 1, titled "BWR Jet Pump Assembly Failure" was sent to the following licensees on May 13, 1980 for action:

Cincinnati Gas and Electric Company  
 Zimmer (50-358)

Cleveland Electric Illuminating Company  
 Perry 1, 2 (50-440, 50-441)

Commonwealth Edison Company  
 Dresden 2, 3 (50-237, 50-249)  
 La Salle 1, 2 (50-373, 50-374)  
 Quad-Cities 1, 2 (50-254, 50-265)

Consumers Power Company  
 Big Rock Point (50-155)

Dairyland Power Cooperative  
 LACBWR (50-409)

Detroit Edison Company  
 Fermi 2 (50-341)

Illinois Power Company  
 Clinton 1, 2 (50-461, 50-462)

Iowa Electric Light & Power Company  
 Duane Arnold (50-331)


Northern Indiana Public Service Company  
 Bailly (50-367)

8009090117

MAY 15 1980

Northern States Power Company  
Monticello (50-263)

Sincerely,



Helen Pappas, Chief  
Administrative Branch

Enclosure: IE Bulletin No.  
80-07, Supplement No. 1

cc w/encl:  
Mr. D. W. Kane,  
Sargent & Lundy  
Central Files  
Reproduction Unit NRC 20b  
Local PDR  
NSIC  
TIC

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT  
WASHINGTON, D.C. 20555

SSINS No.: 6820  
Accession No.:  
8005050055 *dup*

May 13, 1980

IE Bulletin No. 80-07  
Supplement No. 1

BWR JET PUMP ASSEMBLY FAILURE

C. Reporting Requirements

The information in Items A.3, and B.1, is requested under the provisions of 10 CFR 50.54(f). Accordingly, you are requested to provide within the time periods specified in these items, written statements of this information, signed under oath or affirmation.

These reports should be submitted to the Director of the appropriate NRC Regional Office and a copy should be forwarded to the NRC Office of Inspection and Enforcement, Division of Reactor Operations Inspection, Washington, D.C. 20555.

Approved by GAO, B180225 (R0072); clearance expires 7-31-80. Approval was given under a blanket clearance specifically for identified generic problems.

RECENTLY ISSUED  
IE BULLETINS

Bulletin No.	Subject	Date Issued	Issued To
80-13	Cracking In Core Spray Spargers	5/12/80	All BWR's with an OL
80-12	Decay Heat Removal System Operability	5/9/80	Each PWR with an OL
80-11	Masonry Wall Design	5/8/80	All power reactor facilities with an OL, except Trojan
80-10	Contamination of Nonradioactive System and Resulting Potential for Unmonitored, Uncontrolled Release to Environment	5/6/80	All power reactor facilities with an OL or CP
80-09	Hydramotor Actuator Deficiencies	4/17/80	All power reactor operating facilities and holders of power reactor construction permits
80-08	Examination of Containment Liner Penetration Welds	4/7/80	All power reactors with a CP and/or OL no later than April 7, 1980
80-07	BWR Jet Pump Assembly Failure	4/4/80	All GE BWR-3 and BWR-4 facilities with an OL
80-06	Engineered Safety Feature (ESF) Reset Controls	3/13/80	All power reactor facilities with an OL
80-05	Vacuum Condition Resulting In Damage To Chemical Volume Control System (CVCS) Holdup Tanks	3/10/80	All PWR power reactor facilities holding OLs and to those with a CP
79-01B	Environmental Qualification of Class IE Equipment	2/29/80	All power reactor facilities with an OL
80-04	Analysis of a PWR Main Steam Line Break With Continued Feedwater Addition	2/8/80	All PWR reactor facilities holding OLs and to those nearing licensing